

# 11/6/13 CCR Proposed Sampling Locations

## Location #1 (S. of Star Rd) on 10<sup>th</sup> St

→ East side of the road could yield one sample location due to the crop on the land. Chat has been removed or washed out from the field. No evidence after ~20 ft off road or chat.

→ On west side, the line continues very degraded but chat is still present. Several RR pins + metal is present. (Check extent of access post. 10<sup>th</sup> street → could yield ~3 sample locations if access included.

## Location #2 (on Greelawn east of 10<sup>th</sup> St)

→ North side of the road has a short, shallow dip right at the road (~10 ft from) and the line continues. Heavily vegetated and degraded line

→ South side is even more degraded and vegetated. Very little visible chat under leaf cover on ground



Location

(Residential)

Location #3 on Wilkes Ave in  
between 2nd + 4th St. after  
diagonal 3rd St

West side of the road is sparsely  
vegetated with tall grasses  
that is visible with degraded  
wood trees and some igneous  
rocks in the mix.

Line continues until active line  
East side is exposed "assumption"  
with no vegetation. On a map,  
it shows up as a road.

Chert is spread out in varying  
distances from the line's  
original setting.

Followed chert road/trail to  
Grant Street.

On EAST/N side of Grant St. →  
heavily vegetated on each side  
of the tracks. Track is clear  
and chert is visible.

Continues east and curves  
north past an industrial  
plant

Location #4 on Ballard just south  
of 19th Street ~~at the~~  
in between barn & house

10<sup>th</sup> St  
old  
so  
removed  
re  
the  
t.  
strives  
chert  
cont.  
post.  
d  
17  
= 10<sup>th</sup> St  
at  
the  
y  
line  
ed  
order

line might still exist?  
Access is impeded by swamp <sup>large piled</sup>  
West of the road has been <sup>cut off</sup>  
remediated by BS PD contractor  
East side has a gate w/ lock  
but chat/line ore exposed  
throughout curve. Visible  
for 3+ sample locations.  
sparsely vegetated w/ grasses.  
Potential cattle issue. —  
Check w/ landowner.

Location #5 on SE 30th Street, just  
west of Bullard / 10th Street.

North side of road where  
Abenamy property w/ line  
was remediated as part of  
BS PD remediation contract.  
→ north side is gated & locked  
and has a road.

~~Fract~~<sup>line</sup> / chat is visible and  
no vegetation.

Continues through property  
and is visible for 3+ sample  
locations - check w/ surv.

land owner to gate access.

No evidence of tracks, signs, etc  
→ maintained as a farm  
road

Boxer Springs for lunch 12 PM

Handwritten header text

Section 1: [Illegible]

[Illegible handwritten text]

Section 2: [Illegible]

[Redacted]

[Illegible handwritten text]

[Redacted]

[Illegible handwritten text]

[Illegible handwritten text]

[Illegible handwritten text]

[Redacted]

[Redacted]

[Illegible handwritten text]

[Redacted]

[Redacted]

[Illegible handwritten text]

[Redacted]

[Illegible handwritten text]

[Illegible handwritten text]

[Redacted]

[Illegible handwritten text]

[Illegible handwritten text]

Dec 4  
2003

Sold to Freeman

SW Rock & Chat Co. 1999  
sold to [redacted]

Youngman Rock 1991  
sold to SW Rock & Chat

[redacted] sold to  
SW Rock & Chat

> large

[redacted] - SW corner-ish  
[redacted] - Appraisers)  
Section 18 along 69 each side  
→ metal-sided warehouse  
trees??  
→ old mining buildings  
at the corner 69 & 69 [NE]  
- the same as the ones [corner]

1986

→ Trece Truett bought a building in May 2012 from the red box area in that corner of 1986 pic

C&S Equipment & Sales owned

→ Section 18 the washers & corporation structures

↳ 1984 Nanco end @ 3:30pm

Location 6 → visited previously in Crestline w/ pics of!

Location # 7 SE 80th <sup>South of Old Hwy 96</sup>

line is left as a grade with flooded valleys on each side

→ on east side of road = some hills created with the chert

→ on both sides of the road chert is visible w/ some leaf litter and heavily vegetated and trees along the line.

NE  
corner

Location #8 on 90<sup>th</sup> St south of  
old Hwy 96

West side of the road is clear for  
a great distance until halted  
by a bale of hay  
Not treed or vegetated.

Chat is visible → access road  
maintained  
by land owner  
east side of the road is the same  
with higher grassy areas on either  
side of the line of exposed  
chat. There is a gate & chained  
for access.

end @ 4:30pm

